

LIGO Laboratory / LIGO Scientific Collaboration

<https://dcc.ligo.org/T1500549>

LIGO

April 1st, 2016

04/-01 HAM-ISI Model Update

Release Notes

Version 2

Hugo Paris, Brian Lantz

Distribution of this document
Advanced LIGO Project

This is an internal working note
of the LIGO Laboratory

California Institute of Technology
LIGO Project – MS 18-34
1200 E. California Blvd.
Pasadena, CA 91125
Phone (626) 395-2129
Fax (626) 304-9834
E-mail: info@ligo.caltech.edu

Massachusetts Institute of Technology
LIGO Project – NW22-295
185 Albany St
Cambridge, MA 02139
Phone (617) 253-4824
Fax (617) 253-7014
E-mail: info@ligo.mit.edu

LIGO Hanford Observatory
P.O. Box 1970
Mail Stop S9-02
Richland WA 99352
Phone 509-372-8106
Fax 509-372-8137

LIGO Livingston Observatory
P.O. Box 940
Livingston, LA 70754
Phone 225-686-3100
Fax 225-686-7189

LIGO-T1600090

This update is to bring the the HAM-ISI model up to speed with the [T1600062](#) BSC-ISI update. This document lists the items requested in [SEI aLog 987](#) and comments. It also describes how they were assessed or postponed. Please refer to [T1600062](#) for screenshots and details.

1) frame updates:

- a) store drive channels at same rate as HAM-ISI model (2048)

N/A

- b) store GS-13s, cart basis, at full model rate

GS13 signals were stored at 2048 in both the commissioning and the science frame. This was switched to matching the model rate.

- c) stop storing multiple copies of the ground STS-2s

Ground STS2 signals are already stored in the STS library block. The following channels were removed from the master model's list of DQ channels.

SENSCOR_GND_STS_{DOF}_FIR_IN1

Note: those used to be stored at a sample rate of 512.

2) fix the blend glitch - temp fix checked in, make a real fix.

BTL temp fix in place. Larger fix pending.

3)

- a) implement the 10 sec mandate on the BIO for LLO

Add BIOWAIT block to the BIO signal path in the WD block. This was already performed in isi2stagemaster.mdl by BTL.

- b) add monitor channels for the individual HAM bios

issue only appears at Stanford. S1:ISI-HAMX_BIO_IN_CD_V1_STATUS are blank on HAM-ISI WD screens. → tried recompiling with latest models from the SVN on 03/10. Problem still here but not relevant for the sited.

4) fix low case names of the STS-2 commands in the BIO_OUT block

N/A

5) make an MEDM screen with the STS-2 commands and monitors

N/A

6) St1-2 FF and St1 compensation

<https://alog.ligo-la.caltech.edu/SEI/index.php?callRep=882>

add path to compensate all of the st2 drive.

N/A

7) change the way the T240 gain switching is done

https://services.ligo-wa.caltech.edu/integrationissues/show_bug.cgi?id=915

N/A

8) increase number of allow saturations for BSC-ISI Wds to match the HAM-ISI numbers.

https://services.ligo-wa.caltech.edu/integrationissues/show_bug.cgi?id=1125

Already in place.

9) add "saturations since model start" epics channel to SEI watchdogs

https://services.ligo-wa.caltech.edu/integrationissues/show_bug.cgi?id=1134

LIGO-T1600090

Created a new version of ISIWDSATCOUNT.c called ISIWDSATCOUNT_vb.c. The new version computes the number of saturations since last model restart.

→ We created a new c-code file to allow updating models separately without impacting models that may still rely on the old code.

Note: svn up-ed hepitemplate and made sure it was not using ISIWDSATCOUNT.c.

Switched WD block function call from ISIWDSATCOUNT_.c to ISIWDSATCOUNT_vb.c and added new SAT_SINCE_RESTART epics output and related reset momentary input to master model.

10) Allow recording the mass positions for the STS-2s

N/A

11) add Reflected memory path for gnd STS-2s so we can isolate against only the differential motion

Next update

12) a) the outdated, top-level, binary IO blocks should be upgraded.

JeffK's Request. To be clarified for next update

12) b) we'd like to upgrade the reset momentary to use the

`$(userapps)/cds/common/src/LONG_PULSE.c`

c-code where the duration of the pulse is user-defined such that it can send out the desired ~0.5 [sec] voltage pulse. (This is presumably what the additive STS2_Reset_ADD was trying to do).

No STS on HAM-ISIs, no re-centering BIO command, N/A

12) c) All of the cdsEpicsIn parts need to have their channel names capitalized in order to be functional.

N/A

12) d) The CAL, SIGSEL, and PERIOD should be changed to epicsBinIns, such that they can appear as rocker

N/A

13) create ISI to SUS point library block to be placed on the top level model

Block already created as part of the BSC-ISI [T1600062](#). Installed at LHO by HughR ([LHO alog #26363](#)).

14) [SEI aLog 943](#)

14) a) Add an SCSUM block after the ST2, SENSCOR block, just like what is in place for the GND to ST1 sensor correction in the ST1 block

N/A

14) b) Store the new sensor correction channels

`$(IFO):ISI-$(OPTIC)_ST2_SCSUM_T240_$(DOF)_IN`

`$(IFO):ISI-$(OPTIC)_ST2_SCSUM_CPS_$(DOF)_IN`

at 256 [Hz]

In place before update. Channels stored in commissioning frames only. At sample rate of 256.

c) Store the pre-existing channels feed forward channels

`$(IFO):ISI-$(OPTIC)_ST1_FF12_$(DOF)_IN1`

at 256 [Hz] in order to help diagnosis and characterization of these control paths.

Already in place. Stored in both the commissioning and science frames at 2048.

LIGO-T1600090

15) Employ tilt sensor correction from ST1 to ST2, recently proven successful in augmenting translational degrees of freedom (see [LHO aLOG 25623](#))

N/A

16) BSC-ISI: Remove T240 signals going into ST2 SENS COR. Instead pick off 6x signals of T240-L4C blends and send them into ST2 SENS COR + send resulting drive signals to ST1 to allow compensating for ST2 drive there - to make it available to compensate for back-reaction.

N/A

17) ISI WD request - let the ISI model run w/o tripping if the SUS model goes down give a 60 sec. window to operator. (HughR)

Next Update

18) Last minute update – we need to add the SUSPOINT_EUL and CAL_CART channels to the DQ list. Same rate as saved by SUS.

Done

19) Do this for the HAMS as well ← This is what we will do next.

Purpose of this update. Done.

20) Remove user Dackill – approved

Removed the user dackill from the HAM-ISI master model.

Made sure the reset all button of the MEDM screen was still working. It does reset the WD, even though it returns the following error:

Error: ECA_TIMEOUT - User specified timeout on IO operation expired at /opt/rtds/userapps/release/guardian/CaTools.pm line 175.

```
--S1:ISI-HAMX_DACKILL_RESET-- didn't connect.
```

...Indeed this channel doesn't exist anymore.

→ We will leave the MEDM screens as they are so the WD+Dackill can still be reset on platforms that haven't been updated yet.

→ This remains to be done on the BSC-ISIs.