



CALIFORNIA INSTITUTE OF TECHNOLOGY
 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

DCN No. E010028-00-D

SHEET 1 OF 1

DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D970550-C-D	GUIDE ROD FIXTURE, BEAMSPLITTER OPTICS	D

CHANGE DESCRIPTION (FROM/TO): Move mounting holes of top blocks.

Sheet 2: Zone G6: From 2X, 3.000 to 2X, 3.500

From 2X, 1.058 to 2X, 1.308

From 3.672 to 3.422

Sheet 3: Zone E6 and E3: From 3.000 to 3.500

Zone D7 and D2: From .750 to .500

Zone D8 and C1: From 1.556 +/- .001 to 1.806 +/- .001

Zone D6 and D3: From 1.241 to 1.491

REASON FOR CHANGE: a mistake was made in the machining of this piece that facilitated moving the mounting holes. This DCN documents the as-built configuration

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)

- No hardware affected (record change only)
- List S/Ns which comply already:
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
-
-
-
-

DCN DISTRIBUTION (X=Incl. docs)

Coyne	Barish	Coles
Raab	Lazzarini	Lindquist
Stapfer	Sanders	Shoemaker
Whitcomb	Tyler	Weiss
	Zydowicz	
Barton		
Jones		
Heefner		
X Romie		
Fritschel		

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (if yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie <i>J. Romie</i>	2-9-01		
TASK LEADER: J. Romie <i>J. Romie</i>	2-9-01		
GROUP LEADER: <i>D. Coyne</i>	<i>3/29/01</i>		
DCC RELEASE:			



CALIFORNIA INSTITUTE OF TECHNOLOGY
 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

DCN No. **E010028-00-D**

SHEET **1** OF **1**

DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D970550-C-D	GUIDE ROD FIXTURE, BEAMSPLITTER OPTICS	D

CHANGE DESCRIPTION (FROM/TO): Move mounting holes of top blocks.

Sheet 2: Zone G6: From 2X, 3.000 to 2X, 3.500
 From 2X, 1.058 to 2X, 1.308
 From 3.672 to 3.422

Sheet 3: Zone E6 and E3: From 3.000 to 3.500
 Zone D7 and D2: From .750 to .500
 Zone D8 and C1: From 1.556 +/- .001 to 1.806 +/- .001
 Zone D6 and D3: From 1.241 to 1.491

REASON FOR CHANGE: a mistake was made in the machining of this piece that facilitated moving the mounting holes. This DCN documents the as-built configuration

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION (X=incl. docs)
<input checked="" type="checkbox"/> No hardware affected (record change only)	Barish Coles Lazzarini Lindquist Raab Sanders Shoemaker Stapfer Tyler Weiss Whitcomb Zydowicz Barton Jones Heefner X Romie Fritschel
<input type="checkbox"/> List S/Ns which comply already:	
<input type="checkbox"/> List S/Ns to be reworked or scrapped:	
<input type="checkbox"/> List S/Ns to be built with this change:	
<input type="checkbox"/> List S/Ns to be retested per this change:	
<input type="checkbox"/>	
<input type="checkbox"/>	

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie <i>J. Romie</i>	2-9-01		
TASK LEADER: J. Romie <i>J. Romie</i>	2-9-01		
GROUP LEADER:			
DCC RELEASE: <i>Linda P. ...</i>	4-18-01		