



DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D010131-A-D	Magnet Fixture for 40m Small Optics	B
D960001-C-D	Small Optic Suspension Assembly	D
D010197-A-D	40m ETM Left Ear	B
D010198-A-D	40m ETM Right Ear	B
D010199-A-D	40m ITM Left Ear	B

CHANGE DESCRIPTION (FROM/TO):

D010200-A-D 40m ITM Right Ear B

D010131 - Table 1, switch part numbers in "left side block" column with part numbers in "right side block" column.
 D960001 - add D010131 as a ref in parts list
 D010197 - D010200. In side view (shows left/right orientation of bushing) show bushing sticking out of opposite side.

REASON FOR CHANGE: Right side and left side wedge orientations were mixed up in design process.

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)

- No hardware affected (record change only)
- List S/Ns which comply already: Parts already reworked.
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
-
-
-
-

DCN DISTRIBUTION (X=incl. docs)

Coyne	Barish	Coles
Raab	Lazzarini	Lindquist
Stapfer	Sanders	Shoemaker
Whitcomb	Tyler	Weiss
	Zydowicz	
Barton		
Jones		
Heefner		
X Romie		
Fritschel		

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie	4-28-03		
TASK LEADER: Alan Weinstein			
GROUP LEADER: Dennis Coyne			
DCC RELEASE:			