INITIATOR

DATE 7-23-98

L190-E980594-00-D

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. 2972141

CUSTOMER DRAWING NO. D972139

DRAWING TITLE Pitch Flexure Arm

REVISION: FROM A TO B

HYTEC INCORPORATED

DESCRIPTION OF CHANGE (Simple Phrase, Identify Dims If Possible):

Change the locator pin & slot dimensions from .3105 .3102 to .3109 .3105

REASONS FOR CHANGE:

The 1/4-20 shoulder bolt has a max shoulder diameter of .3105 which would lead to a .0003 in interferance between hole & shaft.

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL
None		

IFY COGNIZANT DESIGNER: Roger Smith

NOTIFY COGNIZANT ENGINEER: Erik Swensen

APPROVED: Jim Thompson