



# DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D960499-B-D	LOS CHAMFER STOP	C
D970562-n/a-D	BEAMSPLITTER CHAMFER STOP	A
D970563-n/a-D	BEAMSPLITTER SAFETY STOP	A
D990690-n/a-D	LOS SAFETY STOP	A
D990691-n/a-D	LOS3 CHAMFER STOP	A

**CHANGE DESCRIPTION (FROM/TO):**

D990019-00-D	FLUROEL TIP, SMALL	A
D990020-00-D	FLUOREL TIP, LARGE	A
D990148-00-D	FLUOREL TIP, 1/4-20	A

D960499: Complete redesign. From screw made of conductive teflon to silver coated stainless screw with fluo-rel tip lodged in counterbore at the end.

Others: Initial Release

**REASON FOR CHANGE:** D960499: The conductive Teflon flaked during cleaning operations.

**ACTION:**  Incorporate change  Attach DCN to drawing(s)  Other action (specify):

**DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)**

- No hardware affected (record change only)
- List S/Ns which comply already:
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
- These drawing revisions detail the as-built configuration for all IFOs.
- 
- 
- 

**DCN DISTRIBUTION (X=incl. docs)**

Coyne	Barish	Coles
Raab	Lazzarini	Lindquist
Stapfer	Sanders	Shoemaker
Whitcomb	Tyler	Weise
Zydowicz		
Barton		
Jones		
Heefner		
X Romie		
Fritschel		

**SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT?**  No  Yes (if yes, enter Change Request number )

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie <i>J. Romie</i>	2-12-01		
TASK LEADER: J. Romie	2-12-01		
GROUP LEADER: <i>D. Coyne</i>	<i>2/26/01</i>		
DCC RELEASE:			



CALIFORNIA INSTITUTE OF TECHNOLOGY  
 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

DCN No. E010026-00-D

SHEET 1 OF 2

## DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D960499-B-D	LOS CHAMFER STOP	C
D970562-n/a-D	BEAMSPLITTER CHAMFER STOP	A
D970563-n/a-D	BEAMSPLITTER SAFETY STOP	A
D990690-n/a-D	LOS SAFETY STOP	A
D990691-n/a-D	LOS3 CHAMFER STOP	A

**CHANGE DESCRIPTION (FROM/TO):**

D990019-00-D	FLUROEL TIP, SMALL	A
D990020-00-D	FLUOREL TIP, LARGE	A
D990148-00-D	FLUOREL TIP, 1/4-20	A

D960499: Complete redesign. From screw made of conductive teflon to silver coated stainless screw with fluorel tip lodged in counterbore at the end.

Others: Initial Release

**REASON FOR CHANGE:** D960499: The conductive Teflon flaked during cleaning operations.

**ACTION:**  Incorporate change  Attach DCN to drawing(s)  Other action (specify):

**DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)**

- No hardware affected (record change only)
- List S/Ns which comply already:
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
- These drawing revisions detail the as-built configuration for all IFOs.
- 
- 
- 

**DCN DISTRIBUTION (X=incl. docs)**

Coyne	Barish	Coles
Raab	Lazzarini	Lindquist
Stapfer	Sanders	Shoemaker
Whitcomb	Tyler	Weiss
	Zydowicz	
Barton		
Jones		
Heefner		
X Romie		
Fritschel		

**SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT?**  No  Yes (If yes, enter Change Request number )

APPROVALS	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie <i>J. Romie</i>	2-12-01		
TASK LEADER: J. Romie <i>J. Romie</i>	2-12-01		
GROUP LEADER:			
DCC RELEASE: <i>J. Romie</i>	4-18-01		