2	1GO		0.77	em i i		DCN No. E060175-00-C			
California Institute o						DCN 110. E000175-00-C			
Massachusetts Institute of Technology Document Change Notice (DCN)					Sheet	Sheet 1 of 1			
DOCUMENT No. (DOC-REV-GP.ID)							NEW REV		
(DO	C-REV-GI.I							KL V	
D050093-B1		Synchrono	Synchronous Timing Generator					B2	
СНА	NGE DESC	CRIPTION (FROM	I/TO):						
Durir		ne VCXO showed po		atch up. To prevent	this, the follo	wing cl	hanges should	be	
	From	То							
C3	NL	100pF							
C4	NL	100pF							
R13	10k	2k							
R14	10k	1.62k							
R15	NL	9.53k 100pF							
REA	SON FOR	CHANGE:							
ACTI	ON:	☐ Incorporate Chang	e	ach DCN to Drawings	Other A	Action (s	specify):		
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS) DCN DISTRIB							N DISTRIBUTION	Ī	
☐ No hardware was affected (record change only):						bbott schel	R. Abbott Heefner	Coyne Marx	
List S/Ns which comply already:					McC	Carthy	J. Myers	Raab	
List S/Ns to be reworked/scrapped:					Weis		Schwinberg Whitcomb	K. Watts Wooley	
List S/N's to be built with this change: List S/Ns to be retested per this change: Zucker									
SAFE	ГҮ, COST, SC	HEDULE, REQUIREME	NTS IMPACT	Г? ПО П	YES (If YES, ent	er CR (C	CB) or TCP (TRI	B) #)	
	APF	PROVALS:	DATE	OTHER APPROVA	LS (SPECIFY)			DATE	
ORIGINATOR: Joshua R. Myers			5/3/06						
TASK LEADER:									
GRO	UP LEAD	ER:							

DCC RELEASE: