	DCC Number: E080081-00-X
advancedligo	Date Prepared: 2-15-2008

Originator		Cognizant Engineer	Ext./Phone#	Project	Account Number
Tom Evans	Ken Ma	ason	(509)372-8116	Enhanced LIGO	
				SEI HAM	
Dwg/Part Number	Rev	Part Descripti	on / Material	Serial Nu	ımber Qty
D 071471	С	GS-13 Flex Plate			2
Used In (next higher assemb	ly): SEI	HAM		I	

•	Sed in (next inguer assembly): SEI HAW	
	Vendor Name	PO/Contract Number
T		

Data Package, Receiving/Inspection Remarks:

Inspection Required Y/N	Visual Damage Y/N	Comments	Name/ Initials	Date Comp.
			·	

## **Process Flow:**

#	Operation	<b>Start Date</b>	Work Area	Instructions	Name/ Initials	Date Comp.
1	Clean		LLO	clean per LIGO document E960022-B	T.E.	2-1-08
2	Vacuum Bake		LLO	per E960022, 200C, 48 hrs	T.E.	2-6-08
3	Control Point		LLO	Review/Approve RGA scan	BO'R	2-6-08

N.B.: A copy of this traveller must be submitted to the DCC each time the original is shipped with the associated part(s) and when the traveller has been completed.

ad	Va	n	CO	d	lia	7
au	Va	щ	CC	u	iig.	9

DCC Number: E080081-00-X
Date Prepared: 2-15-2008


#	Operation	Start Date Work A	rea Instructions	Name/ Initials	Date Comp.		
4	Wrap & Tag vacuum clean	LLO		T.E.	2-8-08		
	parts						
5	Ship and Deliver/File		Please send to:	BO'R	4-21-08		
	paperwork		LIGO Livingston				
			File one copy of traveler with the DCC.				
			Note: Ship original traveler with these parts.				
EN	END: Go to Traveler or procedure associated with next higher assembly processing						

Special Instructions (Handling/Packaging Constraints, Remarks, etc.) or Notes:


After cleaning these parts, give to Joe Hanson for LLO HAM6 ISI build.	


N.B.: A copy of this traveller must be submitted to the DCC each time the original is shipped with the associated part(s) and when the traveller has been completed.











RGA of Oven Load with calibrated leak (main turbo valved off)

