



DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D970267-B-H	PEM, ELECTRO MAGNETIC SHAKER PLATE, ^{Base} 5.142	C
D970272-B-H	" " " SIDE	C
D970273-A-H	" " " Support BAR	B
D970279-A-H	PEM, ELECTRO MAGNETIC SHAKER MASS	B

CHANGE DESCRIPTION (FROM/TO):

D970267 Remove Lower set of B holes. change Qty From 10 to 8
 D970272 Reduce width of plate From 5.142 TO 3.824.
 D970273 Add 4 A holes. From 4 to 8
 D970279 Change Location of A holes on the top and bottom sides.

REASON FOR CHANGE:

to accommodate supporting the shaker mass while in the horizontal direction. Correct for interference problem.

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)

- No hardware affected (record change only)
- List S/Ns which comply already:
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
-
-
-
-

DCN DISTRIBUTION (X=incl. docs)

Althouse	Barish	Coles
X Coyne	Lazzarini	Lindquist
Lucas	Sanders	Shoemaker
Stapfer	Tyler	W
Weiss	Whitcomb	

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: <i>MJ Smith</i>	2-20-98		
TASK LEADER: <i>Alex</i>	2-20-98		
GROUP LEADER: <i>[Signature]</i>	20 Feb 98		
DCC RELEASE: <i>[Signature]</i>	2-26-98		