

INITIATOR BW

DATE 10-27-98

LIQO-8980567-00-D

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. D972001 + 503

CUSTOMER DRAWING NO. D972103

DRAWING TITLE COARSE X-Y FLUTTING

REVISION: FROM C TO D



HYTEC
INCORPORATED

DESCRIPTION OF CHANGE (Simple Phrase, Identify Dims If Possible):

The 2 screws that hold the pneumatic
mtg block should be 1/4-20 x 3,
not 1/4-28 x 2

REASONS FOR CHANGE:

Draw. error

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: Roger

NOTIFY COGNIZANT ENGINEER: Erick S

APPROVED: Tim