

INITIATOR VC KROVIN'S

DATE 8-22-98

L190-8980583-00-D

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. _____

CUSTOMER DRAWING NO. 972001

DRAWING TITLE L160 BSC TOP Assembly

REVISION: FROM _____ TO A



HYTEC
INCORPORATED

DESCRIPTION OF CHANGE (Simple Phrase, Identify Dimensions if Possible): ITEM 25 call for 64

1/13 x 2.25 LG SOC Need 3 different items: ① Qty 16 HEX 1/13 x 1.75 LG
HEAVY DUTY?
1/2" Fender washer (CONNECT TO ITEM 2); ② Qty 32 SOC 1/13 x 1.75 LG (CONNECT TO EX HOLES ZONE D-8)
972131, ③ Qty 16 1/2-20 x 1.75 LG SOC (CONNECT TO ZONE D-6 EX HOLES 972111)

3/8-24

REASONS FOR CHANGE: 2.25" is too long, bolts will protrude; need HEX w/
flanges too limit distortion of 972111; need 1/2-20 to connect to 1/2-20
washer part 972111

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: Rogan
NOTIFY COGNIZANT ENGINEER: Talv
APPROVED: [Signature]

Submitted