



TTL Enable 0 ohms R14 & R122
 omit R9
 omit K1

24 V Digital omit R14 & R122
 omit R9
 Place K1 Relay 6_GH

Always ON omit R14 & R122
 0 ohms R9 or jumper P62
 omit K1

TTL Enable 0 ohms R15 & R123
 omit R7
 omit K2

24 V Digital omit R15 & R123
 omit R7
 Place K2 Relay 6_GH

Always ON omit R15 & R123
 0 ohms R7 or jumper P63
 omit K2

