	8	7	6		5	ţ	4	3	I
D	 NOTES CONTINUED: SCRIBE, ENGRAVE, OR MECHANICALLY STAMP (NO DYES OR INKS) A UNIQUE THREE DIGIT SERIAL NUMBER START AT 001 FOR THE FIRST ARTICLE AND PROCEED CONSECUTIVELY. BAG AND TAG PARTS WITH THEIR DRAWING PART NUMBER. REVISION, VARIANT OR 'TY (IF APPLICABLE), AND QUANTITY. IF PARTS ARE TOO SMALL TO SCRIBE, BAGGING AND TAGGING ALONE SUFFICIENT. EXAMPLE (PART): 01-v1 EXAMPLE (PART): 01-v1 EXAMPLE (TAG): DXXXXXX-VY, TYPE-XX, QTY: TBD APPROXIMATE WEIGHT = .16 LB [.07 KG]. ALL PARTS SHALL BE MANUFACTURED IN ACCORD WITH UGO SPECIFICATION E0900364. ALL MATERIAL IS TO BE VIRGIN MATERIAL (i.e. NOT REPAIRS SHALL BE MADE UNLESS APPROVED IN ADVANC WRITING BY LIGO, REFER TO LIGO-E0900364. NO REPAIRS SHALL BE MADE UNLESS APPROVED IN APVANC WRITING BY LIGO, CREFER TO LIGO-E0900364. NO REPAIRS SHALL BE MADE UNLESS APPROVED IN APVANC WRITING BY LIGO CONTRACTING OFFICER'S REFACL OLICICUMSTANCES CAN BE REVIEWED IF / 1 ATTENTION OF LIGO CONTRACTING OFFICER'S REFACL CIFICATION RS1-2 CARRIAGE. ALL TAPPED HOLES: USE .005 OVERSIZE DRILL & TAF 	YPE" IS ANCE WELD CE IN A ADVANCE, AND IN WRITING, S AND PRESS FIT INSERT REPAIRS SE MADE WITH VIRGIN MATERIAL. WHEN BROUGHT TO THE PRESENTITIVE (COTR) THROUGH RT D LIGO-E0900364.		F - Contraction of the second		JNC ↓ .30 290	(.30)—	SECTION F-F	
FOCUS CARRIAGE, PART PDM REV: X-010, DRAWING PDM REV: X-012		.25	E62	2X 	10-24 UNC ↓ 0 0	.35	SECTION		
D1001952 aLIGO TMS DEL-TRON RS1-2 F	٥	7		NO DIMENSIONS ARE IN INCHES TOLERANCES: .XX ± .10 .XXX ± .005 ANGULAR±°	TES AND TOLERANCES: (UNLI 1. INTERPRET DRAWING 2. REMOVE ALL SHARP I 3. DO NOT SCALE FROM 4. ALL MACHINING FLUI AND FREE OF SULFUR, SI MATERIAL	SS OTHERWISE SPECIFIED) PER ASME Y14.5-1994. DGES, R.02 MIN. 10 RAWING. DS MUST BE FULLY SYNTHETIG LICONE, AND CHLORINE.	C, FULLY WATER SOLUBLE FINISH N/A μinct	NEXT ASSY	dlogy Hnology System AOS

