





Rev	Description	Date
A	Initial Release	11/00
A1	1. Changed LT1028 to OP27 2. Changed C25, C26, C49, C50 to 47pF, 500V	7/01
A2	Added Radd1, Radd2, Radd3, Radd4 to terminate board bias inputs.	4/04
A3	DCN E050154-00 changes the compensation components on the PA-85 driver stages from 47pF/10 ohms to 5000pF/330 ohms to cure an observed oscillation in the 7 to 8 MHz band	6/05