



- NOTES:  
 1. ALL DIMENSIONS ARE IN INCHES  
 2. REMOVE ALL BURRS AND BREAK SHARP EDGES TO A MINIMUM OF 0.015 IN  
 3. DRAWING NUMBER TO BE CLEARLY MARKED ON THE PART ITSELF  
 4. THOROUGHLY CLEAN TO REMOVE ALL OIL, GREASE, DIRT & CHIPS  
 5. APPLY PRIMER AND PAINT (BLACK) TO ALL VISIBLE SURFACES EXCEPT FOR TEFLON FACING

ALL DIMENSIONS ARE IN INCHES  
 TOLERANCES: X.XX: +/- 0.03"  
 X.X: +/- 0.1"

D010227-00-D  
 OVERHEAD BSC CROSSBEAM  
 BRACKET (LEFT HAND)  
 LIGO PROJECT  
 L JONES 10/4/01