

DCN No. E010369-00-D
SHEET 1 OF 1

	_	_			
DOCUMEN	IT CHANG	E NOTIC	E (DCN)		
DOCUMENT No. (DOC-REV-GP. ID)			TITLE		NEW REV.
D970545-B-D L	LOS2 BRACKET, SENSOR/ACTUATOR				
D970546-B-D I	LOS2 SAFETY STOP BRACKET FRONT				С
D970547-B-D	LOS2 SAFETY STOP BRACKET REAR				С
	LOS2 BRACKET, SIDE SENSOR/ACTUATOR, LEFT				C
D970549-B-D LOS2 STIFFENER ADAPTER PLATE					C
CHANGE DESCRIPTION (FROM/TO)	:				
D970557-A-D I	OS3 SENSOR	ACUATOR B	RACKET, SIDE		В
	OS3 BRACKE		14 101121, 5122		В
			BRACKET, REAR		В
D970570-B-D	LOS2 BRACKI	ET, SIDE SEN	SOR/ACTÚATOR, RI	GHT	С
D980373-A-D I	OS3 SAFETY	STOP BRACI	KET, FRONT		В
	OS3 SAFETY		*		
REASON FOR CHANGE: J-shape	d fillet on the se	ections to be w	elded were needed to a	achieve requirer	nent of full
penetration weld.	d lillet on the se	ections to be w	ciaca were needed to t	temeve requirer	
ACTION: X Incorporate change	Attach DCN t	o drawing(s)	Other action (specify):		
<u> </u>			,		
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)				DCN DISTRIBUTION (X=incl. docs)	
No hardware affected (record change only)				Baris	h Coles
X List S/Ns which comply already: A]] Coyne Lazzarini Raab Sanders					•
List S/Ns to be reworked or scrapped: Stapfer Tyler We					Weiss
List S/Ns to be built with this change: Whitcomb Zydowicz					wicz
List S/Ns to be retested per this change:					
Jones					
Heefner					
X Romie					
Fritschel					
SAFETY, COST, SCHEDULE, REQUI	REMENTS IMPACT?	No 🗍	Yes (If yes, enter Change Rec	quest number)
APPROVALS:		DATE	OTHER APPROVAL	S (specify)	DATE
ORIGINATOR: J. Romie		12/18/01			
TASK LEADER: J. Romie		12/18/01			
GROUP LEADER:					
DCC RELEASE:]		