

DCN No.	E040002-00-D					
SHEET	1	OF	1			

DOCUME	NT CHANG	E NOTICE	(DCN)			
DOCUMENT No. (DOC-REV-GP. ID)			TITLE		NEW	
D960002-C-D	SENSOR/ACTU	IATOD DI ATE			REV.	
D960002-C-D D960005-C-D	RIGHT SIDE P				D	
D700003-C-D	KIGITI SIDETI	LAIL			ע	
CHANGE DESCRIPTION (FROM/T	······································					
D960002 - For the 40m Re		PRM and SRM	) only From Av. 296 D	ΙΔ ΤΗΡΙΙ to ΔΧ 37	5 DI Δ	
THRU.	cycling willfols (	I KWI and SKWI	) omy. 110m 4x, .270 D	1A 111KO, 10 4A, .57	JDIA	
D960005 - For the 40m Be	amsplitter only. A	Add cutout, .5"	x 1.00" near hole for se	nsor/actuator.		
REASON FOR CHANGE: D960		•	nt of sensor/actuator po	sition		
D960	005 - clearance fo					
ACTION: Incorporate change	e Attach DCN t	to drawing(s)	Other action (specify):			
	DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)  DCN DISTRIBUTION (X=in					
No hardware affected (record change only)  List S/Ns which comply already:  Coyne						
List 5/145 Willon Comply already.						
List S/Ns to be reworked or scrapped:  X List S/Ns to be built with this change: see above						
<ul><li>✓ List S/Ns to be built with thi</li><li>✓ List S/Ns to be retested per</li></ul>		е				
List 3/Ns to be retested per	this change.					
SAFETY, COST, SCHEDULE, REQ	UIREMENTS IMPACT?	? / No / Y	es (If yes, enter Change Reque	est number	<u> </u>	
APPROVALS:		DATE	OTHER APPROVALS		 TE	
ORIGINATOR: J. Romie		1-8-04		,	_	
TASK LEADER:		1 0-0-				
GROUP LEADER:						
DCC RELEASE:						