



# DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
see page 2	see page 2	

**CHANGE DESCRIPTION (FROM/TO):** Initial Release

Initial Release

**REASON FOR CHANGE:** Initial Release

**ACTION:**  Incorporate change     Attach DCN to drawing(s)     Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION
<input checked="" type="checkbox"/> No hardware affected (record change only)	Althouse    Barish    Coles
<input type="checkbox"/> List S/Ns which comply already:	X Coyne    Lazzarini    Lindquist
<input type="checkbox"/> List S/Ns to be reworked or scrapped:	Sanders    Shoemaker
<input type="checkbox"/> List S/Ns to be built with this change:	Stapfer    Tyler    [redacted]
<input type="checkbox"/> List S/Ns to be retested per this change:	Weiss    Whitcomb    [redacted]
<input type="checkbox"/>	Zydowicz
<input type="checkbox"/>	Raab
<input type="checkbox"/>	Romie X
<input type="checkbox"/>	
<input type="checkbox"/>	
<input type="checkbox"/>	

**SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT?**     No     Yes (if yes, enter CR (CCB) or TCP (TRB) no. )

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie	8/18/98		
TASK LEADER:			
GROUP LEADER: <i>D. Coyne</i>	8/21/98		
DCC RELEASE: <i>[Signature]</i>	8/21/98		



# DOCUMENT CHANGE NOTICE

CHANGE DESCRIPTION (FROM/TO):

Document No.	TITLE	New Rev.
D970506-00-D	Large Optic Suspension Structure Assembly - Beamsplitter	A
D970541-00-D	LOS2 Top Plate	A
D970542-00-D	LOS2 Bottom Plate	A
D970543-00-D	LOS2 Front Stiffener	A
D970544-00-D	LOS2 Side Stiffener	A
D970545-00-D	LOS2 Bracket, Sensor/Actuator	A
D970546-00-D	LOS2 Bracket, Safety Stop, Front	A
D970548-00-D	LOS2 Bracket, Sensor/Actuator, Left	A
D970570-00-D	LOS2 Bracket, Sensor/Actuator, Right	A
D970549-00-D	LOS2 Stiffener Adapter Plate	A
<del>D970563-00-D</del>	<del>LOS2 Safety Stop Bracket Rear</del>	<del>A</del>

D970547-00-D

DB