





# LVEA Equipment Room Rack C1

41 U




## Color Key

- 1 U  Installed
- 1 U  Ready for installation
- 1 U  Built but not fully tested
- 1 U  Still being built
- 1 U  Not even started building
- 1 U  TBD

Status as of 20 September 2011

LIGO-D1001427-v3

## LVEA Equipment Room Rack C2



# LVEA Equipment Room Rack C3

