



# Cryo-Pump Baffle Wipe Down and Experiment

## 19 Aug 2011



Above and below: Discoloration



Pictures to the right: Spots where coating has already chipped off.



Above: The Experiment

